

Attached is the vehicle inspection report for the VIN
WMW51GA0507R46545, created on 15/04/2026, 16:58, requested by:
Ilari Pulli, Motor Trade Inh. Ilari Pulli, Test Account bis 30.04.2026 (FJ)

This account is part of the following organisation: **Motor Trade Inh. Ilari Pulli**

VIN:	WMW51GA0507R46545
Mileage:	27,611 km
Date:	15/04/2026, 16:58
Car brand:	MINI
Car series:	Countryman
Car model:	Countryman U25
Build year:	2024
Fuel type:	Electric
Report ID:	69dfa792926d4a4bc3d70c65
Adapter ID:	RED--CCEE36

Battery capacity (SoH)

99.99 %

Estimated remaining range: **433 km**
WLTP range of comparable vehicles: **433 km**

Digital



The OBD diagnosis enables the reading of error codes and operational data from the vehicle's control units. This technology supports the identification of potential issues and irregularities. However, it should be noted that not all errors or issues in all control units can be fully detected through OBD diagnostics. Carly Solutions GmbH & Co KG and TÜV NORD Mobilität GmbH assume no liability for undetected errors that are beyond the scope of this diagnostic technology.



Analysis method

The analysis is based on the communication quality between Carly hardware and the on-board interface, live battery data and previous usage information of the traction battery. Plausibility checks, AI procedures and big data analyses enable a precise assessment of the battery condition by comparing collected data and optimizing the accuracy of the results.



99.99 %

State of Health

58 %

State of Charge

Attached is the vehicle inspection report for the VIN
WMW51GA0507R46545, created on 15/04/2026, 16:58, requested by:
Ilari Pulli, Motor Trade Inh. Ilari Pulli, Test Account bis 30.04.2026 (FJ)

This account is part of the following organisation: **Motor Trade Inh. Ilari Pulli**

High voltage system measurements

State of Health	99.99 %
State of Charge	58 %
Battery Temperature	22.73 °C
Maximum Cell Temperature Deviation	0.54 °C
Maximum Cell Temperature	22.97 °C
Battery Voltage	300.49 V
Maximum Cell Voltage Deviation	4 mV

Car photos

Total: 3

